												· <u></u> _
Work Ord Thursday, Octob							7	>U"	PLI	CAT	E	Page 1
Item ID: Revision ID:	D4018-041				Accept				s	etup Star	t	
Item Name:	Short Basket I	id Assembly (350)							Stop		
Start Date: Required Date: Reference:	10/21/2010 10/22/2010	Start Qty: 1. Req'd Qty: 1.				Cust It Custon						
Approvals:	Process Pla	n: _ M/	Date:	10-10-2	D Tooling: SPC (Y/N):		Date:		R	tun Star Stop		
Sequence ID/ Work Center II	D	Operation Description			Set Up/ Run Hours	Tool	ID Too	l# Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr										
D4018	С											
100 Large Fab Large Fab			o emble ribs, wel	d as per dwg D4	0.00 0.00 018 using DT9607B ets as per dwg D4018				S.	4-10/1	0/28	
		ins 3- tack ***ma	spect before weld k weld mesh on b	ling mesh basket as per dw		olate before				0		

110

QC9- Inspect visual per QSI004- Fusion Welds

0.00

Memo

Quality Control

0.00

Dart /	Aeros	pace	Ltd
--------	-------	------	-----

Duit Aci	Sopuce	Liu				i.				
W/O:			W	ORK ORDER CHANGES	3	1				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						i I				
			· · · · · · · · · · · · · · · · · · ·				· · · · · · · · · · · · · · · · · · ·			
Part No		PAR #:	Fault Cat	egory:	NCR: Yes	s ! N	o DQ	A :	_ Date: _	
	R	esolution:	Dispositi	on:	QA: N/C	Clos	ed:		Date:	·
NCR:		V	ORK ORE	DER NON-CONFORMAN	CE (NC	R)				
DATE	STEP	Description of NC		Corrective Action Section			Verific	ation	Approval	Approval
DATE	SIEF.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	е	Section	on C	Chief Eng	QC Inspector
						1				
						!				
						;				
						i				
						•			*	
				•		<u>.</u>				

Hand Finishing

Page 2 Thursday, October 28, 2010 3:37:36 PM Item ID: D4018-041 Accept Setup Start **Revision ID:** Stop **Item Name:** Short Basket Lid Assembly (350) **Start Date:** 10/21/2010 Start Qty: 1.00 **Cust Item ID: Required Date:** 10/22/2010 Req'd Qty: 1.00 **Customer:** Reference: Run Start Process Plan: ____ Date: Tooling: **Approvals:** Date: Stop Date: _____ SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. Work Center ID Description **Run Hours** Qty Code Qty Number Stamp 120 QC5- Inspect part completeness to step on W/O 0.00 & voliols Memo Quality Control 130 Black Sandtex(Ref:4.3.5.7) per QSI005 4.3 0.00 Powdercoat 0.00 Memo Powder Coating *** mask sides of hinge prior to powdercoat*** Start Time: 0.10. Oven Temperature: Finish Time: 8:40 Wing Walk as per dwg QS1005 4.4 Batch 11 5 7 9,00 => H 140 HandFinish 0.00 Memo

1- Mask data plate and apply wing walk on outside surface of mesh as per dwg

2- install label

	Dart	Aeros	pace	Ltd
--	------	-------	------	-----

W/O:			WORK ORDER				r. 5		
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
					!				
					i I				
Part No	:	PAR #:	Fault Category:	NCR: Yes	! [No DQ	A:	Date:	·	
	Resc	olution:	Disposition:	QA: N/C C	losed:		Date:		

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B	1	Verification	Annroval	Approval			
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Section C	Approval Chief Eng	Approval QC inspector			
				•							
					İ						
					!						
		·									
	1	1	1 1			1		1			

Work Order ID 63126

Thursday, October 28, 2010 3:37:36 PM



Page 3

Item ID:

D4018-041

Accept

Setup Start



Revision ID:

Item Name:

Short Basket Lid Assembly (350)

Start Date:

10/21/2010

Start Qty: 1.00

Req'd Qty: 1.00 **Required Date:** 10/22/2010



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date: ____ Tooling:

S 44 5 54

Set Up/

Run Hours

Date:

Run

Start

Stop

Stop



Date:____

SPC (Y/N):

Date:

Reject

Insp.

Work Center ID

150

Sequence ID/

QC

Quality Control

Operation **Description**

QC3- Inspect Part Finish

Memo

0.00

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Number

Stamp

160

170

QC



Packaging

Packaging

Identify as per dwg & Stock Location:

Memo

0.00

0.00

10/11/03/2 MF 10-11-3

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

W/O:		,	WO	RK ORDER CHANGI	ES				, ,
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
) 				
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQA	:	_ Date: _	
	Re	esolution:	Disposition	:	_ QA: N/C CI	osed:		Date: _	<u></u>
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC	Corrective Action		on B	Verific	ation	Approval	Approval
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		n C	Chief Eng	QC Inspector
									:
	,								
						i			
						ĺ			
						!			
						1	-		
						!			
I .			1 1		T T				1

Picklist Print

Thursday, October 28, 2010 3:37:36 PM

Work Order ID: 63126

Parent Item: D4018-041

Parent Item Name: Short Basket Lid Assembly (350)

Start Date: 10/21/2010

Start Qty: 1.00

Required Date: 10/22/2010

Required Qty: 1.00

Comments:

IPP RevA: new issue DD 09.11.30 verified by:EC

per dwg revA 10.03.15 verified by:EC

ied by:EC IPP Rev:B as IPP Rev:C as per dwg RevB

DD 10.04.16 verified by:EC

IPP Rev:D as per dwg revC DD 10.08.18

verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4018-1		Manufactured	No			100	Each	4.0000	2	² /y	0/10/5	9	
				Location	- !	Loc	<u>Oty</u>	Loc Code					
				WA			4		_				
					59252		4		_	\bigcirc	<u></u>		
D4018-3		Manufactured	No			100	Each	4.0000	2	2	10/10	129	
				Location	!	Loc	<u>Oty</u>	Loc Code					
				WA			4		_				
					59253		4		_	(a)	_		
D4016-3 Hinge Half, Lid		Manufactured	No			100	Each	10.0000	3	3 dr.	110/10	/29	
				Location	!	Loc	<u>Oty</u>	Loc Code					
				ST116			6		_				
					60723		6		_				
				WA			4		_				
					60548		4		_	(3)	_		

Dart Aerospace L	td
------------------	----

		T						· ·	
W/O:			W	ORK ORDER CHANGE	ES				j •
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						<u>}</u>			
						!			
						 - 			
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Disposition	on:	QA: N/C C	losed:		Date: _	
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NCI	₹)			
DATE	STEP	Description of NC Section A Corrective Action Initial Action Description			on B		cation	Approval	Approval
4	0121	Section A	Chief Eng	Action Description Chief Eng	Sign Date		on C	Chief Eng	QC Inspector
•									
						;			
				·		i			
,	ļ					<u> </u>			
					·	;]			
						(,

Thursday, October 28, 2010 3:37:36 PM

Work Order ID: 63126 Parent Item: D4018-041 Parent Item Name: Short Basket Lid Assembly (350) Start Date: 10/21/2010 Required Date: 10/22/2010 Start Qty: 1.00 Required Oty: 1.00 D4018-5 Manufactured No 100 Each 21.0000 Rib Location Loc Oty Loc Code WA 21 59929 21 D4035-041 Manufactured No 100 Each 4.0000 Lid Rib Assembly, Fwd (350 Basket) Location Loc Oty Loc Code WA 60546 2 61066 D4035-043 Manufactured No 100 Each 4.0000 Lid Rib Assembly, Aft (350 Basket) Location Loc Qty Loc Code WA 60475 2 61067 2 D2581 Manufactured No 100 Each 31.0000 Mounting Bracket Location Loc Qty Loc Code WA 31 60470 11 61953 20

W/O:			W	ORK ORDER CHANGES	\$			ı,
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			,			· 		
				•				
Part No	•	PAR #:	Fault Cat	egory:	NCR: Yes	No DQA:	Date: _	
	R	esolution:	Disposition	on:	QA: N/C CI	osed:	Date: _	
NCR:	,	,	WORK ORE	ER NON-CONFORMAN	ICE (NCF	R)		
DATE	STEP	Description of NC		Corrective Action Section		Verificatio	n Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspector
						1		
						!		
				·				

Picklist Print

Thursday, October 28, 2010 3:37:36 PM


Page 3

Work Order ID: 63126 Parent Item: D4018-041 Parent Item Name: Short Basket Lid Assembly (350) **Required Date: 10/22/2010 Start Date:** 10/21/2010 Start Qty: 1.00 Required Qty: 1.00 D4020-7 Manufactured No 100 1.0000 Each Mesh (350 Basket Short, Lid) Location Loc Qty Loc Code FG 59610 D4021-3 Manufactured 100 No Each 5.0000 Data Plate Location Loc Qty Loc Code WA 5 56050 59987 2 60734 2 D2728-3 Manufactured 140 Each 0.0000 B#115050 Dart Logo label


W/O: DATE	STEP	PRO		ORK ORDER CHANG	iES				Annroyal	
DATE	STEP	PRO	OCEDUDE OU						Approval	1
			PROCEDURE CHANGE By				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•							_ <u>i</u> 			
							<u> </u>			
Part No	:	PAR #:	Fault Cate	egory:	_ NCR	: Yes	No DQ	A:	Date: _	
	Re	esolution:							Date: _	
NCR:	!	•	WORK ORE	DER NON-CONFORM	ANCE	(NCR	l)'			
DATE	STEP	Description of NC	Corrective Action Sec			Sign &		cation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Date	Section C		Chief Eng	QC Inspector
							i			

NOTE: Date & initial all entries


H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE




									Ĺ				
W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		47											
							İ						
							i						
	-												
	<u> </u>						,	<u> </u>	I				
		PAR #:	Fault Cate	NCR: Yes No DQA: Date:									
			lution: Disposition:										
NCR:		V	VORK ORE	ER NON-CONF	FORMAN	CE (NCF	R)		,				
DATE	STEP	Description of NC	Corrective Action Section B			Sign 8	Verific		Approval	Approval			
DAIL	Section A		Initial Chief Eng	Initial Action Description Chief Eng Chief Eng			Section	on C	Chief Eng	QC Inspector			
										1			
) !						
					·		i						
										ļ			
							Î						
							!			}			



W/O:			,	, •								
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
	,											
						<u> </u>						
						ı						
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _				
			tion: Disposition: (
NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP	Description of NC		Corrective Action Section		Verification		Approval	Approval			
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		on C	Chief Eng	QC Inspector			
						ŧ į						
						İ						
						1						
						<u> </u>						
							•					
	1 1		1 1		ı	1		1 .	l			



W/O:		WORK ORDER CHANGES									
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						ľ					
Hill of the A											
						j I					
						:					
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DC	A:	Date:			
		esolution:	Dispositio	n:	_ QA: N/C	Closed: _					
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NC	R)					
DATE	STEP	Description of NC		ion B	Verif	cation	Approval	Approval			
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		ction C	Chief Eng	QC Inspector		
						j					
									1		
						,					
					·				,		



Dart Aerospace	Ltd
----------------	-----

W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	PROCEDURE CHANGE			,	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									•			
	:					;						
Part No		PAR #:	Fault Category: NO			es N	o DQA:		Date:			
	R	esolution:	Disposit	QA: N/0	Clos	sed:	Date:					
NCR:		1	WORK OR	DER NON-CONFORT	MANCE (N	CR)						
DATE	STEP	Description of NC		Corrective Action Section B			Verifica	tion	Approval Chief Eng	Approval QC Inspector		
DAIE SIEF		Section A	Initial Chief Eng	Action Description Chief Eng		gn & ˈ ate	Section C					
						ļ						
										,		
								<u> </u>				
						,						
							1					